



# Tech Info Library

## Macintosh IIci: Causes for IIci Incompatibilities (Part 3 of 4)

Article Created: 30 March 1990  
Article Last Reviewed: 8 July 1992  
Article Last Updated:

### TOPIC -----

This is part three of a four part article detailing the changes which caused the compatibility problems the Macintosh IIci faced. A significant number of Macintosh IIci compatibility problems were related to the improvements outlined below. Keep in mind that the majority of applications were not affected by these changes and that most of those that were have been updated.

### DISCUSSION -----

#### Leading Causes for Macintosh IIci Incompatibilities (Con't)

##### 3) 32 bit QuickDraw in ROM

The Macintosh IIci is the first CPU to incorporate 32-bit QuickDraw in ROM. With previous systems users had the option of installing 32-bit QuickDraw in RAM through the addition of an INIT file to their system folder. Although 32-bit QuickDraw was engineered for high compatibility with the original QuickDraw and Color QuickDraw programmer's interfaces, certain programming practices could lead to problems with this new software. Users of the 32-bit QuickDraw INIT could optionally deactivate the software if there proved to be a compatibility problem. Because 32-bit QuickDraw is in ROM on the Macintosh IIci, it cannot be defeated.

##### - Video card problems

Generally, existing video cards have no compatibility problems with 32-bit QuickDraw. However, newer cards designed to take advantage of 32-bit QuickDraw's features such as 16 and 32-bit direct color pixels and large frame buffers need to follow a special initialization sequence at startup to allow the card's special features to be activated after the 32-bit QuickDraw INIT has been loaded. On the Macintosh IIci, 32-bit QuickDraw (and the new Slot Manager) are in ROM, so a simpler, but different, startup sequence needs to be executed. Some third-party developers unaware of this alternate sequence were incompatible with the Macintosh IIci when it was first introduced.

## - Software Problem

One major change in 32-bit QuickDraw is that the frame buffer memory is always accessed in 32-bit addressing mode rather than the 24-bit addressing mode used by previous versions of QuickDraw. This allows the applications to access frame buffers up to 16MB in length, as opposed to 1MB with non-32-bit versions of color QuickDraw. This additional frame buffer address space is becoming increasingly important as the use of 24-bit color becomes more prevalent.

For a user to benefit from this 32-bit addressing mode they must install a video card capable of taking advantage of it. In turn, a video card possessing these capabilities must test the system to determine if 32-bit QuickDraw is present or not. If it is present then 32-bit QuickDraw capabilities of the card will be enabled, which means, among other things, the card will expect to be accessed in a 32-bit addressing mode. If 32-bit QD is not present most cards will default to the 24-bit addressing mode. In this way, a new card possesses the flexibility to adjust to whichever QuickDraw environment it finds itself in.

In a system where 32-bit QuickDraw is present and there is a 32-bit QuickDraw capable card installed, there is the potential for incompatibilities with certain applications that directly address, (i.e. bypassing QuickDraw) the video frame buffer. A number of paint applications fall into this category. Previously, these applications could directly access all frame buffers in 24-bit addressing mode and know that they would work. However if an application is running on a system with 32-bit QD installed and a 32-bit QuickDraw capable video card is also installed and the application attempts to directly address the frame buffer a problem occurs. The application is attempting to access a 24-bit address in 32-bit addressing environment. In this case, the address request will be redirected to the 24-bit alias of the 32-bit buffer and you end up with garbled screen data or a system that hangs.

Keep in mind this situation can occur on any machine with 32-bit Quickdraw and a 32-bit QuickDraw capable card installed. The difference is that on a machine with 32-bit QuickDraw as an INIT in RAM, the INIT can be deactivated and the system will revert to 24-bit addressing for the frame buffer (although it will lose new features). Because on a Macintosh IIci, 32-Bit QuickDraw is in ROM, it cannot be defeated, so these applications will not work correctly, and require revision. Once again, this problem occurs only with new video cards that expect 32-bit QuickDraw.

**IMPORTANT NOTE:** The revision to HyperCard from 1.2.2 to 1.2.5 was required to address this issue.

## 4) Built-in video

One of the features of the Macintosh IIci's built-in video design is the fact that it is self configuring, which means that all the user has to do is plug the monitor into the video port and the system automatically

recognizes what monitor is attached and configures itself accordingly. Offering this feature required that there be some type of monitor identification scheme included in the design. The scheme used in the Macintosh IIci is to designate three of the 15 pins within the video connector for monitor identification. This gives the system a 3 bit value (3 pins pulled high or low, where high = 1 and low = 0) for identifying up to 8 different conditions, (7 different monitors + 1 no-monitor condition).

It is significant to note that this scheme originated with the introduction of the revised 4•8 bit video card introduced in the spring of 1989. It is also important to note that it is utilized on both the 8•24 and 8•24GC cards, and in the future it will be utilized in all future systems which incorporate built-in video and in all future video card designs from Apple.

Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5432