



Tech Info Library

PCI-Based Power Macintosh: Issue with SCSI ID 5 (4/96)

Article Created: 6 February 1996

Article Reviewed/Updated: 18 April 1996

TOPIC -----

This article describes an issue affecting SCSI ID 5 on the following Power Macintosh series computers:

Power Macintosh 7200/75
Power Macintosh 7200/90
Power Macintosh 8500/120
Power Macintosh 9500/120
Power Macintosh 9500/132

DISCUSSION -----

On previous PCI-based Power Macintosh computers, there was an issue affecting SCSI ID 5, which may cause the computer to lock-up or the light on the SCSI 5 device to remain on constantly. The symptoms were most apparent when using array software, a scanner (when scanning), or a CD-ROM drive (without a CD-ROM disc inserted).

The issue was fixed in the SCSI Manager and was included in System 7.5.3. Newer PCI-based Power Macintosh computers which ship with System 7.5.3 should not have this problem, and previous PCI-based Power Macintosh computers can upgrade to System 7.5.3 by installing System 7.5 Update 2.0, which is available on the online services.

These articles can help you locate the software update mentioned here:

- "Where To Find Apple Software Updates" - Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" - Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

Article Change History:

18 Apr 1996 - Updated technical information.

Copyright 1996, Apple Computer, Inc.

Keywords: hts,kppc

=====

This information is from the Apple Technical Information Library.

19960419 15:09:15.00

Tech Info Library Article Number: 19309