



Tech Info Library

H-Series ColorMonitor IIc/e P/C: F901 Fuse Keeps Blowing

This article last reviewed: 15 December 1987

NOTE: Check the serial number. This fix is only for:
ColorMonitor IIes with S/N less than Y029000
and
IIc ColorMonitors with S/N less than Y048650.

PROBLEM DESCRIPTION: F901 (3.15 amp fuse) on the main logic PCB
of H-Series ColorMonitor IIc and IIes is blown.

CAUSE: A "special" medium blow higher ampere rating fuse needs to
be installed.

CURE: Contact your local support center and ask them to send you an
upgrade fuse kit.

If this cure does not resolve the problem, go to the Tech Procedures
to obtain a General Troubleshooting procedure.
Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1432