



Tech Info Library

Apple IIc Monitors : Wavy Video Display

Article Created: 19 December 1985
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Video display exhibits a "waving" or "rippling" effect.

CAUSE: Stand alone power supply manufactured prior to 4584 (i.e. the 45th week of 1984).

CURE: Check the stand alone power supply date code. If manufactured prior to 4584, exchange the power supply.

This repair is eligible for warranty coverage to those customers who have purchased AppleCare for their system. For all others the repair cost responsibility lies with the customer.

If this cure does not resolve the problem, go to the Tech Procedures to obtain a General Troubleshooting procedure.
Copyright 1990 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1607