



Tech Info Library

ImageWriter II Problem/Cure: Prints Darker on One Side

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: The ImageWriter II prints darker on one side of the page than on the other.

CAUSE: The print head may not be parallel to the platen.

CURE: Install appropriate shims from the ImageWriter II shim kit. The part number for this kit is listed in the Price Pages of the Service Programs binder.

If the above cure doesn't fix the problem, search on GTS and the product's name to obtain a general troubleshooting procedure.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1887