



Tech Info Library

ImageWriter LQ: ROM Upgrade Service Program

This article last reviewed: 20 September 1989

TOPIC-----

I have a small network of approximately 10 Macintosh II systems, all using EtherTalk Cards with thinnet wiring. The Ethernet network runs connects through a Kinetics FastPath to a PhoneNET network containing two ImageWriter LQs with LocalTalk PC Cards.

With the original ImageWriter LQ logic board with the ROM version 00 everything worked fine. The printer was available on the network from both the Ethernet side and the PhoneNET side. When the dealer installed a new "Reworked" logic board with a ROM version 02 was installed in the ImageWriter LQ, the Macintoshes could access the printer on the PhoneNET side of the network. However, the printers became invisible on the Ethernet side.

Do you have any suggestions for solving this problem?

DISCUSSION-----

There are problems like the one you described that occur as a result of the ImageWriter LQ ROM Upgrade. To solve the problem, a second service program will replace the main logic board with a newer version. The part number of the board is 661-0563. Use the 02 ROMs and driver version 2.0 for the best results.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4588