



Tech Info Library

Macintosh SE: HD-20SC Setup and Parameter RAM

This article last reviewed: 31 August 1987

When you update the SCSI driver on a Macintosh SE, using HD20SC Setup 1.4, the parameter RAM is affected in three ways:

1. It validates the SCSI ID for the internal drive. If it is determined not to be a "reasonable" number, it is set to zero.
2. The time to wait for the internal drive to start up is checked and set, if necessary.
3. There is a byte that is sometimes overwritten if the system crashes. If this happens, the Macintosh won't start up from the SCSI drive. This byte is reset if necessary.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2367