



# Tech Info Library

## Color Printer: Remove Tape Before Replacing Print Head (10/95)

Article Created: 22 February 1993

Article Reviewed/Updated: 19 October 1995

TOPIC -----

After I replaced the Bubblejet Head Unit in an Apple Color Printer, the printer would not print. What causes this?

DISCUSSION -----

The Apple Color Printer's Bubblejet Head Unit (Service Part Number 661-1685) is shipped with orange tape over the nozzles and small gray cap. These prevent contamination or leakage during shipping.

You must remove this tape before replacing the Bubble Jet Head Unit.

Article Change History:

19 Oct 1995 - Changed distribution status.

18 Mar 1993 - Revised to show additional parts.

Support Information Services

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11600