



# Tech Info Library

## LaserWriter Pro 630: No difference in ROM revisions (7/94)

Article Created: 5 July 1994

TOPIC -----

I had my LaserWriter Pro 630 repaired and the motherboard was replaced. The new motherboard has v2.0 ROMs, whereas my original had v1.0 ROMs. I think the new ROMs have changed the serial settings at switch positions 0 and 2. Does this new set of ROMs change the settings?

DISCUSSION -----

At switch position 0 and 2, both sets of ROMs configure the serial port as documented in the manual:

| Switch Position 0 | 1.0 ROMs   | 2.0 ROMs   |
|-------------------|------------|------------|
|                   | -----      | -----      |
|                   | PostScript | PostScript |
|                   | RS-232     | RS-232     |
|                   | 9600 Baud  | 9600 Baud  |

| Switch Position 2 | 1.0 ROMs   | 2.0 ROMs   |
|-------------------|------------|------------|
|                   | -----      | -----      |
|                   | PostScript | PostScript |
|                   | RS-232     | RS-232     |
|                   | 19200 Baud | 19200 Baud |

Support Information Services  
Copyright 1994, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15743