Tech Info Library

Power Macintosh 7500 & 8500: Vertical Lines Follow Cursor (1/96)

```
Article Created: 10 January 1996


TOPIC ----------------------------------------------------------


I have a Power Macintosh 7500 series computer, and I have recently noticed that
two vertical lines appear to be following the cursor. What could cause this, and
how can I resolve it?


DISCUSSION -----------------------------------------------------


Improper installation of VRAM on Power Macintosh 7500 and 8500 series computers
causes these symptoms. If you have 2 MB of VRAM installed, you must install the
VRAM DIMMs into the slots labeled 1. For example:


1 _____ 1 MB VRAM DIMM
2 _____
1 _____ 1 MB VRAM DIMM
2 _____


Also, you cannot install 3 MB of VRAM. The Power Macintosh 7500 and 8500 series
computer allow only for 2 and 4 MB VRAM configurations.



Support Information Services



Copyright 1996, Apple Computer, Inc.



Keywords:  kppc,hts


==================================================================

This information is from the Apple Technical Information Library.

19960322 07:42:45.00
```

Tech Info Library Article Number: 19204