ABS Tech Note: SNA•ps21 Serial NB Card & Duo Dock (3/95)

Article Created: 24 May 1993
Article Reviewed/Updated: 22 March 1995

TOPIC --

This Technical Note describes problems which may occur when using the
Serial Nubus Card in a Duo Dock.

DISCUSSION ---

Introduction

The Macintosh Slot Manager sometimes does not recognize the presence of a
Serial Nubus Card in the Nubus expansion slot of the Duo Dock.

For Macintosh Applications

If the Serial Nubus Card is not recognized by the slot manager,
applications that use the card will not know that it is present, and users
will not be able to configure the software to run on the card.

Example

The SNA•ps Admin will not be able to find the Serial Nubus Card and the
SNA•ps Gateway can not be configured and loaded.

Article Change History:
22 Mar 1995 - Corrected wording of Duo Dock.

Support Information Services
Copyright 1993-95, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12412