Tech Info Library

AppleCD 300i: Not Booting From Install CD (7/94)

Article Created: 25 July 1994

TOPIC ---

I have a Macintosh 660AV and installed an AppleCD 300i Plus CD-ROM into it. Now
I cannot boot the computer using the Install Me First CD v1.0. What is wrong?

DISCUSSION --

The AppleCD 300i Plus requires Apple CD-ROM extension v5.0. The Install Me First
CD v1.0 has Apple CD-ROM extension v4.0.2 and will not boot the machine. You
must use Install Me First CD v1.2 which has Apple CD ROM extension v5.0.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: hts

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15887