Power Macintosh: Global Village Teleport Problem (1/95)

Article Created: 12 May 1994
Article Reviewed/Updated: 10 January 1995

TOPIC ---

When the Global Village Teleport Serial Control Panel is installed on a Power
Macintosh the system hangs. Global Village is aware of the problem and will
have a fix shortly. Global Village is telling customers that they also need a
fix from Apple for the serial port. Is this true, and when will the fix be
available?

DISCUSSION --

The fix that Global Village is referring to is included in the System Update 3.0
which was recently released. This software is currently available on AppleLink,
as well as the Internet and other online services.

These articles can help you locate software updates mentioned here:

• Where To Find Apple Software Updates
  Lists online services for "free" Apple software updates

• Obtaining Apple Product Support in the USA
  Lists 800 numbers and online services for software updates, Apple
  support information, and a subset of the Apple Tech. Info. Library

Article Change History:
10 Jan 1995 - Revised title, added info on where to find software updates.

Support Information Services
Copyright 1994-95, Apple Computer, Inc.

Keywords: kppc

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15337