Power Macintosh: Don't Drag Copy System Enabler (2/95)

Article Created: 28 March 1994
Article Reviewed/Updated: 27 February 1995

TOPIC ---

In the past, I could drag an enabler off of the Disk Tools disk to replace the
enabler on the hard drive. With the new Power Macintosh computers this doesn't
work anymore.

DISCUSSION --

The Power Macintosh Enabler now joins the System & Finder as NOT being complete
versions on the Disk Tools disk. As such, it also is not recommended to be
dragged from the Disk Tools disk.

Article Change History:
27 Feb 1995 - Revised title slightly.

Support Information Services
Copyright 1994-95, Apple Computer, Inc.

Keywords: kppc, supt, kcompat

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15041