Power Macintosh: Issue Using GPIB Interface Card (6/94)

Article Created: 9 June 1994

TOPIC ---

I have a Power Macintosh 6100 with the NuBus adapter and I want to connect a
JX-450 Professional Color Scanner from Sharp. This scanner needs to be attached
to a NuBus card and it uses the NB-Handler 4.4 software. However when I use
PhotoShop software I receive the error message "GPIB device 7 not found". This
has been configured in the NB-Handler software.

Can you provide the NuBus slot number in the Power Macintosh 6100 when the NuBus
adapter is connected? Is it possible to connect this scanner to this Power
Macintosh model?

DISCUSSION --

The NuBus slot number of the 6100 is $E.

National Instruments (800-433-3488) in Austin, Texas is the manufacturer of the
GPIB Interface for the Sharp Scanner. There is a known compatibility issue
involving the use of this board with Power Macintosh systems. National
Instruments has a fix for their Nubus card for Power Macintosh and can be
contacted directly to upgrade the card.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: kppc

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15575