Tech Info Library

Issue With Stickies & LaserWriter Driver Version 8.4 (9/96)

Article Created: 23 September 1996

DISCUSSION ---

I have seen four different Macintosh computers (two of my own) that appear to
cause Stickies to unexpectedly quit when trying to print a note. This started to
happen on all of these computers after installing LaserWriter v8.4 printer
drivers (desktop printing included). What is wrong?

DISCUSSION ---

Workaround

Apple Engineering is aware of this issue. This is not a printer driver-related
issue. This issue is related to Stickies running out of memory. The easiest way
to resolve this issue is to increase the "Minimum" and "Preferred" sizes of
Stickies by 20K to 140K. This should resolve the problem. Stickies is normally
set to 120K for all three settings: Suggested, Minimum, and Preferred.

Resolution

Future versions of the Stickies application will have the memory requirements in
"Suggested," "Minimum," and "Preferred" sizes set to be 20K greater (at least
140K).

This article was published in the Information Alley on 23 September 1996.

Keywords: ksts,kalley

==

This information is from the Apple Technical Information Library.

19960924 07:31:19.00
Tech Info Library Article Number: 20439