Cyberdog 1.1, OpenDoc 1.1, and Macintosh SE/30 (10/96)

Article Created: 7 November 1996

TOPIC ---

I'm trying to install System 7.5.5, OpenDoc 1.1, and Cyberdog 1.1 on a Macintosh
SE/30. The SE/30 freezes when I try installing OpenDoc and Cyberdog.

I've tried performing a clean system install. Stated the SE/30 with only Apple
extensions with the addition of Mode 32. I have also tried starting with no SCSI
devices, rebuilt the desktop, reset PRAM, start with all extensions off. Is
there a known issue I do not know about?

DISCUSSION --

The first 680x0-based version of Cyberdog is 1.1 which also requires OpenDoc
1.1. OpenDoc 1.1 requires 32-bit ROMs in the computer. Therefore the OpenDoc 1.1
installer does not work on Macintosh II, IIx, IIcx, and SE/30 computers.
Specifically, the OpenDoc 1.1 installer fails with this error, "Illegal
instruction, Co-processor not installed."

Engineering is aware of this issue. They have no time frame for a solution, and
there are no workarounds.

Copyright 1996, Apple Computer, Inc.

Keywords: ksts,knts,kalley

==

This information is from the Apple Technical Information Library.

19961108 08:25:00.00

Tech Info Library Article Number: 20624