System 7: Compact Virtual 3.0 and TransWarp Accelerator Board

Article Created: 7 December 1992

TOPIC ---

I have Compact Virtual 3.0 from Connectix and a TransWarp accelerator board
from Applied Engineering in my Macintosh SE. I have difficulty formatting
floppy disks.

DISCUSSION --

Both Connectix and Applied Engineering say there's a problem with this
configuration when using System 7. They tell us that System 7.1 should
correct it.

If you're using System 7, turn off Compact Virtual when formatting floppy
disks.

To locate a vendor's address and phone numbers, use the vendor name as a
search string.
Copyright 1992, Apple Computer, Inc.

Keywords: SYS7

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10981