LaserWriter Pro 810: No Parallel Support (8/94)

Article Created: 30 August 1994

TOPIC ---

According to information found in the 8/94 version of the Apple Facts product
guide the LaserWriter Pro 810 supports simultaneous connections to LocalTalk,
Ethernet, serial, and parallel interfaces. How do I obtain the parallel
interface?

DISCUSSION --

Early versions of the Apple Facts guide dated through 8/94 contain an error in
the LaserWriter Pro 810 section by referring to a parallel interface on the
LaserWriter Pro 810. The LaserWriter Pro 810 does NOT include a parallel port,
but does include Ethernet, RS-232 serial, and LocalTalk interfaces.

Due to last minute changes in the printer product lineup a parallel printer
interface card for the LaserWriter Pro 810 was inadvertently left on the service
price pages. The part is listed as Apple service part number 661-0850 and is
called a communications card. Although this parallel card can be installed in
the LaserWriter Pro 810 in place of the Ethernet option, Apple does not provide
support for it. The card will be removed from the service price pages shortly.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16142