



Tech Info Library

A/UX: ae0 Interrupt Errors

Article Created: 19 October 1990

Article Change History

08/31/92 - REVIEWED

- For technical accuracy.

TOPIC -----

I am getting various ae0 interrupt errors a few minutes after system boot. NFS and BNET work fine until then.

DISCUSSION -----

Try another slot or try another EtherTalk board. The errors indicate an EtherTalk hardware problem or connection problem.

Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6481