



Tech Info Library

Apple IIGS: RAMDisk Hides Second 3.5 Drive from Pascal 1.3

This article last reviewed: 3 September 1987

When using Pascal 1.3 on an Apple IIGS with two 3.5" drives and a RAMDisk active, the second 3.5" drive can't be accessed. Here's why: using the RAMDisk causes the Apple IIGS SmartPort firmware to move the second drive to slot 2, drive 1. Because Pascal doesn't use this slot as a storage device, you can't access it there.

Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 524