



Tech Info Library

Catalyst 3.0 And Color Monitors

This article last reviewed: 29 September 1988

Catalyst currently does not support monitors that do not have a monochrome mode. Catalyst also does not support the Telex "Peacock" IIC interface with a monochrome monitor.

Some of the problems seem to be caused by the Double-High-Resolution graphics being turned off or disabled. Catalyst 3.0 must have the Double-High-Resolution jumper installed on the 80 column card. Or the display will be totally unreadable.

(NOTE: In cases where the the color bleed is the problem, switch to monochrome mode.)

Recommended Color configurations:

Apple IIe

CARD	MONITOR	TYPE
Apple RGB 80 column	Apple Color 100	RGB
Apple Extended 80 column	Apple Color Monitor IIe	High Res Composite

Apple IIC

CARD	MONITOR	TYPE
N/A	Apple Color Monitor IIC	High Res Composite

NOTE: Apple Computer Inc. is not responsible for the contents of this article.

Quark Technical Support

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1590