



Tech Info Library

Macintosh SE/30: Problems with Ethernet Caused by ADEV

Article Created: March 17, 1991

Article Reviewed Only:

Article Last Updated:

TOPIC -----

My Macintosh SE/30 is freezing up when I use it as a server and router (using an AppleTalk Internet Router and a Kinetics Ethernet card). Could it be that the 68030 Direct Slot card is interfering with the processor in some way?

DISCUSSION -----

We are not aware of any problems using the Macintosh SE/30 in the configuration you describe. The Macintosh SE/30-AppleShare-Router combination is freezing probably because of a problem with the Ethernet card's ADEV. We suggest you try reinstalling the ADEV and see if that solves the problem.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7269