



Tech Info Library

Workgroup Server 8550/132: Time to Ready Workaround (3/96)

Article Created: 8 March 1996

TOPIC -----

This article describes an issue where large and fast hard disk drives do not mount on a Workgroup Server 8550/132 after a cold startup.

DISCUSSION -----

On a Workgroup Server 8550/132 when large drives (2 GB and 4 GB), and fast drives (7200 RPM) are used on both the internal and external SCSI channel, as in a dual-drive configuration, all of the drives may not mount on the desktop from a cold startup. This only occurs with large, and fast drives from a cold restart. This is because the time to ready status is initiated from the drive after the system looks for it.

If this symptom occurs in other situations, its root cause is different.

Workaround

First, use the Startup Disk control panel and deselect all volumes. This delays the system enough for a drive to mount.

Second, select the Restart command from the Special menu. Since the drive will already be spinning, it will respond appropriately to the restarting of the server and mount.

Copyright 1996, Apple Computer, Inc.

Keywords: ksts,knts

=====

This information is from the Apple Technical Information Library.

19960308 15:01:01.00

Tech Info Library Article Number: 19471