



Tech Info Library

LaserWriter IIg: PATHWORKS 1.0 Compatibility (7/93)

Article Created: 13 January 1992

Article Reviewed/Updated: 21 July 1993

TOPIC -----

We're evaluating the LaserWriter IIg and comparing it to similar offerings from HP and QMS. We've successfully tested the IIg over LocalTalk and Ethernet, but the IIg fails to work in a particular serial configuration in which the QMS and the HP work fine. We're using PATHWORKS 1.0 with the IIg connected serially to one of DEC's terminal servers.

DISCUSSION -----

There was a problem when printing to a LaserWriter IIg with PATHWORKS 1.0. DEC has informed us this problem was been fixed with the release of PATHWORKS 1.1, and also that the LaserWriter IIg is supported with release 1.2 as well.

Article Change History:

07/21/93 - To include information on PATHWORKS 1.1 and 1.2.

Copyright 1992-93, Apple Computer, Inc.

Keywords: KCOMPAT

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 9463