



# Tech Info Library

## Apple IIGS Lithium Battery

Article Created: 31 Juy 1987

Article Last Reviewed:17 July 1992

Article Last Updated:

**BEFORE YOU START:** Familiarize yourself with the Apple IIGS Technical Procedures.

**PROBLEM DESCRIPTION:** The lithium battery is leaking and has contaminated the logic board of the Apple IIGS.

**CURE:** Do NOT attempt to clean the board. Do NOT install a new battery. The entire board, with leaking battery, should be returned to Apple and an exchange module installed in the customers computer. The logic board should be returned in the standard anti-static bags and the normal shipping box.

Copyright 1987, Apple Computer, Inc.

Keywords: hts

-----  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2266