



Tech Info Library

Macintosh II: Where To Find Info On The Monitor Shimmer Problem

This article last reviewed: 1 November 1988

Information regarding the Macintosh II monitor shimmer problem is in the "Apple Service Programs" binder in the "Product Notices: Monitors" section on pages 8.5.2 and 8.5.3. The actual adjustment procedure is in the "Apple Technical Procedures" binder (currently volume IV) in the "AppleColor RGB Monitor" section on page 3.7.

Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3367