



Tech Info Library

Macintosh SE/30: Displays Horizontal Lines at Startup

Article Created: 11 August 1989

Article Last Reviewed: 17 July 1992

Article Last Updated:

Problem: The Macintosh SE/30 begins to display short horizontal lines during the first few minutes of operation. The lines tend to appear whenever the mouse is moved. Some applications may make the problem appear more pronounced than others.

Cure: Exchange the logic board and thoroughly retest the system. If the problem continues then consult the Technical procedures manuals for additional information.

Copyright 1989 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2078