



Tech Info Library

UniDisk 3.5: Two Drives Activate

This article last reviewed: 23 November 1987

PROBLEM DESCRIPTION: Two drives activate when booting the Apple IIGS.

BEFORE YOU START: Reverse the positions of the drives so that the second drive is in the first position and vice versa. Proceed to "CURE" if the drives operate normally after reversing the drive positions. Otherwise troubleshoot the problem using the "Symptom Cure Chart" in "UniDisk Technical Procedures".

CURE: Change the Daisy Chain Interface Board in the drive that was originally in the "Drive One" position.

Copyright 1987 Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 186