



Tech Info Library

Apple IIc External Drive : PR#7 Can't Boot

Article Created: 23 January 1986
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Attempt to boot external disk drive PR#7.
No boot action and the words "AppleTalk Offline" appear at the
bottom of the screen.

CAUSE: You may have a logic board which has ROMs compatible with the
UniDisk 3.5 installed. Using PR#7 to boot the external drive is a feature
which was discontinued in these ROMs to make room for other new
features.

CURE: If you are using a UniDisk 3.5 use PR#5 instead of PR#7. If
you are using any other drive, you can not boot from the external
drive.

Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1679