



Tech Info Library

Monitor II Prob/Cure:Vert or Horiz Line or Dot in Display Center

This article last reviewed: 02 November 1988

PROBLEM DESCRIPTION: After the Monitor II has had a chance to warm up, there is a vertical line or a horizontal line or dot going through the center of the display.

WARNING: Turn off and unplug the monitor whenever the case is removed.

CAUSE: 1. The yoke assembly may be bad or misconnected.
2. The electronics module may be bad.

CURE: 1. Check that the gray/brown wires going from the yoke to the electronics module are properly connected.
2. If these wires are properly connected, replace the yoke. Then install the case and turn on the Monitor and check for the faulty display.
3. If the display is still faulty, replace the electronics assembly.

If the above cure doesn't solve your problem, refer to the Tech Procedures to obtain the general troubleshooting procedure for this product.

Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1400