



Tech Info Library

Monitor II Displays Raster Line

This article last reviewed: 29 March 1988

PROBLEM DESCRIPTION: The Monitor II displays a single line across the screen. There is no other display.

CAUSE: Yoke wires might not be connected properly.

CURE: Check the connections for the green/white pair of yoke wires and make sure they are properly connected to the main electronics assembly. At present they are connected to location V-DY (center of main electronics assembly).

Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2069