



Tech Info Library

ImageWriter II Print Quality

This article last reviewed: 28 March 1988

PROBLEM DESCRIPTION: The ImageWriter II produces blurred print when used with the Macintosh in "high quality mode".

BEFORE YOU START: Familiarize yourself with the ImageWriter II Technical Procedures.

CAUSE: The wrong print driver might be installed (such as 2.2).

CURE: Install ImageWriter driver version 2.3 or higher.

OTHER POSSIBLE CAUSES/CURES: "Over inking" might occur when using a new ribbon with porous paper. The thickness lever might be adjusted too far forward. Some applications might require that an older driver be used. Copyright 1988, Apple Computer, Inc.

Keywords: hts

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2020