



Tech Info Library

ImageWriter II won't print from Macintosh

This article last reviewed: 28 March 1988

PROBLEM DESCRIPTION: The ImageWriter II printer won't print when interfaced with the Macintosh and the printer has the 32K Option card installed. The ImageWriter does, however, perform a self-test with no errors.

BEFORE YOU START: Make sure that the print driver has been installed properly on the customers software then attempt to print to a known-good Imagewriter.

CAUSE: The Option card is bad (even though the self-test generates no errors).

CURE: Remove the 32K Option Card and test the printer with the Macintosh connected to the ImageWriter II. Boot a program such as MacWrite and print to the ImageWriter II. Swap the Option Card with a known good one and try to print with MacWrite again.

Refer to General Troubleshooting for the ImageWriter II if the printer still does not print.

Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2025