



Tech Info Library

Macintosh 8•24 GC Card: QuickDraw Printer Problem (11/94)

Article Created: 30 March 1991

Article Reviewed/Updated: 07 November 1994

TOPIC -----

I'm having problems printing from a Macintosh II with a Macintosh Display Card 8•24 GC connected to a LaserWriter SC. When acceleration on the Macintosh Display Card 8•24 GC is on, QuickDraw fill patterns aren't printing properly. I am running System 6.0.5 with LaserWriter SC driver 1.1.

If I turn off acceleration on the Macintosh Display Card 8•24 GC and restart, everything works fine. But restarting each time I want to print is not a satisfactory solution.

DISCUSSION -----

After doing some testing, we discovered that this problem happens with any of Apple's QuickDraw printers. We have told Engineering about the problem and will announce a solution when we have it.

In the mean time, we suggest that you switch off the Macintosh Display Card 8•24 GC's acceleration before printing. You can do this using the card's Control Panel without rebooting or even quitting from an open application. We realize that this isn't a solution, but it is an adequate temporary workaround.

Article Change History:

07 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94 Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7252