



Tech Info Library

PowerBook Computers: Which Modems Came With Them? (10/96)

Article Created: 1 October 1996

Article Reviewed/Updated: 4 October 1996

TOPIC -----

This article contains a list of Macintosh PowerBook computers that came with modems.

DISCUSSION -----

U.S. or International?

Please note that the international (INTNT'L) and United States (US) versions of the PowerBook computer models listed in the chart below may vary in the types of modems that shipped with them. You should also be aware that all of the international versions of the modems have mini-DIN 8 ports instead of RJ-11 ports, each of which was designed for the appropriate country-specific DAA type.

Begin_Table

Macintosh PowerBook Computers

100, 140, 145, 145B, 170 (INTNT'L)	- Apple Fax Data Modem (2400 bps data, 9600 bps fax)
100, 140, 145, 145B *, 170 (US)	- Apple Fax Data Modem (2400 bps data, 9600 bps fax)
145B * (US)	- Global Village Powerport Bronze Fax modem (2400 bps data, 9600 bps fax) (service part number)
150 ** (US & INTNT'L)	- Did not include an internal modem.
160, 165c, 180, 180c	- Apple Express Modem (14.4 bps)
Duo 200 & 2300 series	

- (US & INTNT'L) - Apple Express Modem for Duo (14.4 bps)
- 500 Series (INTNT'L) *** - Apple Express Modem II (14.4 bps)
- 500 Series (US) - Global PowerPort Village Mercury for the PowerBook 500 Series (19.2 bps)
- 5300 & 190 series (US & INTNT'L) - Do not support internal modems. However, PC (PCMCIA) Card modems can be used in the built-in PC Card slot.

- * - Some early PowerBook 145B models did not include a modem at all while others shipped with the Apple Fax Data Modem.
- Some later PowerBook 145B Plus Pack models shipped with a third-party modem:

PowerBook 145B Plus Pack

- + One version of the PowerBook 145B Plus Pack shipped with a built-in Global Village Powerport/Bronze Fax modem.
- + Other versions of the version of the PowerBook 145B Plus Pack were sold with several different bundled software applications, but did not include a modem.

** Although the PowerBook 150 did not include an internal modem, it was shipped with modem patch software from Apple installed in the System folder. This modem patch software is necessary in order for a third-party modem to be installed and utilized in this computer.

*** International versions of the Macintosh PowerBook 500 series computers came with the Apple Express Modem II (not available in the U.S) instead of a Global Village Modem.

End_Table

This article was published in the Information Alley on 4 October 1996.

Article Change History:

04 Oct 1996 - Added Info Alley keyword.

Copyright 1996, Apple Computer, Inc.

Keywords: kpbook,kalley

=====

This information is from the Apple Technical Information Library.

19961007 07:27:03.00

Tech Info Library Article Number: 20493