



Tech Info Library

PowerBook 500 series: Global Village Modem and MacPPP (1/95)

Article Created: 12 January 1995

TOPIC -----

I have a PowerBook 500 with a Global Village Mercury modem and am trying to use a serial protocol like MacPPP. The line drops shortly after I connect. Is there anything I can do about this?

DISCUSSION -----

If you have trouble maintaining a carrier using MacPPP or another PPP using a PowerPort 500, try upgrading to MacTCP 2.0.6 and try using the initialization string AT&F%0\N0 to turn off all compression and error correction.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: kpbook

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17007