



Tech Info Library

PowerBook: Fax/Data Modem Part Number (4/95)

Article Created: 27 October 1992

Article Reviewed/Updated: 06 April 1995

TOPIC -----

The Getting Started manual for the PowerBook and the Standard Retail Price list have different part numbers for the US internal Fax/Data Modem. Which is correct?

DISCUSSION -----

The price list is correct with part number M0970.

The Getting Started manual is incorrect, and shows the part number as M0980. This modem is discontinued.

Article Change History:

06 Apr 1995 - Noted modem is now discontinued, added keyword.

Support Information Services

Copyright 1992-95, Apple Computer, Inc.

Keywords: kpbook,kmanerr

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10582