



Tech Info Library

Macintosh SE/30: 68030 Chip is Soldered to the Logic Board

Article Created: 14 June 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

How is the Macintosh SE/30's processor chip attached to the logic board?

DISCUSSION -----

Early in the Macintosh SE/30's development, the chip was socketed. As a cost reduction enhancement, the 68030 processor chip is soldered onto the Macintosh SE/30's logic board.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8509