



Tech Info Library

Power Macintosh 5200: Tinted Video (1/96)

Article Created: 29 January 1996

TOPIC -----

I have a Power Macintosh 5200 computer, and lately I've noticed that the monitor appears to flicker intermittently. Also, the monitor appears to be discolored. What could be causing this?

DISCUSSION -----

Verify that environmental interference is not the cause of the flickering and discoloration. To do this, try the following suggestions; be sure to look for improvements and changes after following a suggestion:

- Change the location and/or rotate the computer.
- Remove metal objects from the area.
- Look for other environmental influences (power lines, generators, refrigerators, air conditioners).
- Check fluorescent lighting fixtures and transformers, which are also common sources of interference.

If the symptoms you are experiencing do not appear to have an environmental cause, contact an Apple-authorized service provider for additional assistance.

The following computers are in the Macintosh 5200CD family: Macintosh 5200/75 LC, Performa 5200, Performa 5210, Performa 5215, and Performa 5220.

Support Information Services
Copyright 1996, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 19280