



Tech Info Library

Power Macintosh 8100/110: NuBus Changes and Improvements (11/94)

Article Created: 03 November 1994

TOPIC -----

Have there been any changes to the NuBus technology or controller chip used in the Power Macintosh 8100/110?

DISCUSSION -----

The following changes have been implemented in the BART21 controller chip:

BART4 would not allow NuBus Master cards to perform burst reads of main memory (burst writes were fine) unless the bus frequency was a multiple of 40MHz. BART21 corrects this problem.

BART4 would only enable bursting to a slot when the burst enables for all slots were set. BART21 provides burst enable on a slot-by-slot basis.

BART4 only provided access to slots 9-E (and software couldn't take advantage of slot 9 support). BART21 adds standard slot spaces for slots 1-8, and superslot space for slot 8.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16675