



Tech Info Library

Power Macintosh 9500: Unable to Sleep (12/95)

Article Created: 19 December 1995

TOPIC -----

I have a Power Macintosh 9500 and an AppleVision 1710AV Display. Whenever I select Sleep from the Special menu, the screen goes black for a few seconds and then the image comes back on the screen. This happens in every resolution. How can I get the computer to sleep?

DISCUSSION -----

You need an updated System Enabler for the Power Macintosh 9500. System Enabler 701 v1.1 corrects this issue and is available on the Power Macintosh 9500 CD v2.0 or later.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: hts,kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 19085