



Tech Info Library

AudioVision Monitor: Power on Before Power Macintosh (3/95)

Article Created: 27 April 1994

Article Reviewed/Updated: 17 March 1995

TOPIC -----

The AudioVision extension does not appear on restart along bottom of the screen unless I turn on the AudioVision monitor after the Power Macintosh. The AudioVision Sound slider switch is also missing from the Volumes section of the Sound control panel.

DISCUSSION -----

This is a known feature. It is described in the "Additional Tips and Troubleshooting" manual (page 5) for the PowerPC.

Article Change History:

17 Mar 1995 - Corrected wording of PowerPC, made article public.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15202