



Tech Info Library

Power Macintosh: Generic System, Finder & Enabler Icons (5/95)

Article Created: 04 January 1995

Article Reviewed/Updated: 17 May 1995

TOPIC -----

I rebuilt my desktop and then I noticed that icons for the System, the Finder, and the PowerPC Enabler files in my new Power Macintosh 8100/110 are generic in appearance. Everything seems to work fine and rebuilding the desktop again did not resolve the problem.

What can I do to restore the proper icons?

DISCUSSION -----

Problem

This is a cosmetic issue involving the system software which affects the Power Macintosh 6100/66, 7100/80, 8100/100, and 8100/110 computers. Even with the generic icons, the computers are fully functional, and the issue causes no damage to the system software.

Solution

Install the System 7.5 Update 1.0 to correct the issue.

These articles can help you locate the System 7.5 Update 1.0 mentioned here:

- Where To Find Apple Software Updates
Lists online services for "free" Apple software updates.
- Obtaining Apple Product Support in the USA
Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library.

Article Change History:

- 17 May 1995 - Added Power Macintosh 6100/66 and System 7.5 Update 1.0 info.
- 17 Mar 1995 - Corrected PowerPC wording.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: kppc,sys75

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16953