



# Tech Info Library

## Power Macintosh: Internal Speaker Volume (4/95)

Article Created: 27 February 1995

Article Reviewed/Updated: 26 April 1995

TOPIC -----

After upgrading one of our Power Macintosh 8100 computers to an AV version with a CD-ROM, the sound volume from the internal speaker seems lower.

Is this a design to accommodate external amplification, or is it common to all Power Macintosh computers?

DISCUSSION -----

The audio amplification level used by the current Power Macintosh computers is slightly lower than the amplification level of previous Macintosh models. This is due to changes in the chip used to amplify the audio signals.

The use of external amplified speakers is unaffected by the lower volume level since you would use the volume control on the external speakers to control the volume.

Article Change History:

26 Apr 1995 - Minor typographical corrections.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17271