



# Tech Info Library

## HyperCard Serial Port Toolkit: Port B Data Loss Problem

Article Created: 9 May 1989

Article Last reviewed: 15 February 1989

Article Last Updated: 22 June 1992

If you are using the HyperCard Serial Port Toolkit to read data coming into your Macintosh on both serial ports, you may experience problems with Port B (the printer port) losing data. For example, this can happen when inserting a floppy disk.

This problem is not due to either the serial driver or the interrupt priority. The suggested limitation to the printer port of 300 baud communications or less and output-only connections is caused by the Disk Driver. The Disk Driver, which must turn off interrupts during disk accesses, will buffer the modem port only: it does NOT buffer the printer port.

While you can tell the sender to stop sending before writing to a floppy disk, there is no safe and supported way to get around a disk insertion. You should not be using the two ports in this way, since communications of both ports cannot be guaranteed. If the program is to work on a Macintosh II, CommCard from SuperMac Technologies will allow additional serial ports on NuBus which will be free of the system interrupts.

If the stack is to run on a Macintosh Plus or Macintosh SE, use a NetSerial from Shiva or a C-Server from Solana Electronics. HyperCard will continue to think it is talking to the printer port as a serial device. The NetSerial or C-Server software will convert the serial information into AppleTalk packets, which will be converted by the C-Server or NetSerial back into serial communications. These devices contain buffers that will resend any AppleTalk packets lost when interrupts are turned off by the receiving Macintosh, as in the case of an inserted disk. This is the same as occurs during any AppleTalk transaction from the printer port.

Editor's Note 22 June 1992: Solana has discontinued business to our knowledge, so we are unable to refer you to them directly for further information.

For more information, search under: "SuperMac", and "Shiva".

Copyright 1989, 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3644