



Tech Info Library

Power Macintosh:Norton Utilities & Wrong Processing Speed (2/95)

Article Created: 10 February 1995

TOPIC -----

I have a Power Macintosh 8100/100 and the latest version of Norton Utilities. When I run the SYSINFO utility that comes with the Norton Utilities bundle, it tells me that my Power Macintosh 8100/100 is running at 61 MHz and it performs all tests in emulation mode.

Is there something wrong with my computer?

DISCUSSION -----

In an attempt to reproduce your problem, I installed the "System Info" portion of Symantec Corporation's Norton Utilities bundle version 3.1.1, onto a Power Macintosh 8100/100. When I ran the tests, the report said that the CPU is a "PowerPC 601 @ 100 MHz", and that "all the tests were run in native PowerPC code."

You didn't specify the actual version number of the Norton Utilities software that you have. One way to tell if you have the latest version of the software is to check your original Norton Utilities disks. There should be a document named "Norton 3.1.1 ReadMe" on one of these disks.

If you have version 3.1 rather than 3.1.1, I would recommend that you upgrade to version 3.1.1 and run the SYSINFO utility again. You should then receive the correct and expected results.

Note:

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor, Symantec Corporation, for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: ksts,kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17173