



Tech Info Library

Using MIDI software on Power Macintosh computers (3/96)

Article Created: 4 March 1996

TOPIC -----

I am having problems using some MIDI software made by Opcode on my Power Macintosh 7200 computer. Previously, I used this same MIDI software on another Macintosh computer without any problems.

DISCUSSION -----

Opcode's MIDI music software works properly when you update to OMS v2.0.2. You can update your version of OMS by downloading the latest OMS software from Opcode's online FTP or WWW site.

FTP SITE: <ftp.opcode.com>
WWW SITE: <http://www.opcode.com>

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960305 07:36:05.00

Tech Info Library Article Number: 19440