



# Tech Info Library

## Quadra 605 & LC 475: Logic Board Jumper Differences (7/94)

Article Created: 26 October 1993

Article Reviewed/Updated: 26 July 1994

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

The October Service Source DOES NOT make any mention of the jumper on the the LC 475, Performa 475 and Quadra 605 logic board. The problem or difference comes with the placement or absence of the jumper. If the jumper is in place, then System Software sees the logic board as a Quadra 605. If the jumper is removed then System Software sees the logic board as an LC 475.

Service Source needs to be revised to inform the service provider when to use the jumper and when to not use it.

DISCUSSION-----

The jumper difference between the Quadra 605, the LC 475 & the Performa 475 logic boards have already been noted and are scheduled for the next release of Service Source & Module ID.

The Module Identification for 661-1732 (Macintosh Quadra 605 logic board) will have a note saying "Retain the jumper (P/N 517-0546) on the logic board."

The Quadra 605 Price Pages will include the jumper (P/N 517-0546) as an OTHER PART.

This is the same jumper that's listed for the Quadra 900/950.

Article Change History:

26 Jul 1994 - Corrected LC 474 to LC 475.

Copyright 1993-94, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13787