

Apple TV/FM Radio System Requires Video-In Card (3/97)

correctly. What could be wrong?

DISCUSSION -----

The Apple TV/FM Radio System (M4586LL/A) requires a Macintosh Performa or Power Macintosh computer with a video-in card. The video-in card is required even if only the FM Radio Player is used. If the video-in card is not installed, the FM Radio Player will display an error message saying, "The FM radio is not installed in this Macintosh."

While some Macintosh Performa and Power Macintosh computers come with a video-in card pre-installed (for example, the Power Macintosh 5400/120) most of these computers require the purchase of the Apple Video System (M2894LL/D or later).

This article was published in the Information Alley on 12 March 1997.

Copyright 1997, Apple Computer, Inc.

Tech Info Library Article Number:21102